


Preliminary Hand- Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date
3/28/2019 12:00:00 AM to 3/28/2019 1:00:00 AM



Recent Benzene Detections

Location Category	Reading Date	Concentration
Division B	3/28/2019 00:53:05	0.26 ppm
	3/28/2019 00:50:00	0.23 ppm
	3/28/2019 00:12:52	0.43 ppm
Division E	3/28/2019 00:56:06	0.11 ppm
	3/28/2019 00:51:35	0.10 ppm
	3/28/2019 00:47:33	0.11 ppm
	3/28/2019 00:46:06	0.36 ppm
	3/28/2019 00:44:29	0.21 ppm
	3/28/2019 00:42:34	0.34 ppm
	3/28/2019 00:42:32	2.42 ppm
	3/28/2019 00:34:47	2.79 ppm
	3/28/2019 00:33:24	0.29 ppm
	3/28/2019 00:32:57	2.23 ppm
	3/28/2019 00:29:18	6.96 ppm
	3/28/2019 00:21:43	0.76 ppm
	3/28/2019 00:17:15	0.49 ppm
	3/28/2019 00:15:38	0.90 ppm
	3/28/2019 00:12:13	3.46 ppm
Impacted Tank Farm	3/28/2019 00:04:44	4.02 ppm
	3/28/2019 00:47:17	7.25 ppm
	3/28/2019 00:42:52	0.33 ppm
	3/28/2019 00:39:51	1.08 ppm
	3/28/2019 00:36:13	0.13 ppm
	3/28/2019 00:29:31	16.50 ppm
	3/28/2019 00:26:23	0.58 ppm
Industrial Area	3/28/2019 00:19:37	0.10 ppm
	3/28/2019 00:41:48	1.45 ppm
	3/28/2019 00:36:46	2.75 ppm
	3/28/2019 00:32:24	1.45 ppm
	3/28/2019 00:07:01	0.25 ppm
	3/28/2019 00:03:44	0.35 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis.
It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only